

Building Safety Certificate

To,

The Principal,
ST. Thomas School
Dhakuakhana.

Sir,

1. The ST. Thomas School building has been constructed according to the sanctioned Plan.
2. The Building has been constructed as per (i) the detailed structural drawings and structural specifications prepared structural engineer on record. (ii) The details architectural structural drawings and architectural specifications prepared by the architect on record. (iii) Detail drawings and specifications of all services.
3. All materials used in the construction have been tested as provided in specifications and a record of test Report has been kept.

Sign. of Owner
Record

Date.....

Name in block letter :-

Address :-

Sign. of Constitutional Engineer

on Record

Date.....

Name in block letter :-

.....DIPEN BERA.....

Address :-

.....

.....Dhakuakhana T/S.....